


LCAM 5/15 Connections

DC Power Supply: BUS+ 1 Motor Leads: MOTOR+ 4

BUS- 2 MOTOR- 5

Control Signal: J1 - SIGNAL+ 1 Amplifier Enable: J1 – Both Inhibit shorted to Signal Ground

J1 – SIGNAL- 2



Innovation in Linear Motion